296179

[4910-13-U]

DEPT. OF TRANSPORTATION

71111 SEP 111 P 12: 36

Federal Aviation Administration

14 CFR Part 39

19001-2

DEPARTMENT OF TRANSPORTATION (DOT)

[Docket No. FAA-2004

; Directorate Identifier 2004-NM-98-ADI

RIN 2120-AA64

Airworthiness Directives; Saab Model SAAB SF340A and SAAB 340B Series

Airplanes

AGENCY: Federal Aviation Administration (FAA), DOT.

ACTION: Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain Saab Model SAAB SF340A and SAAB 340B series airplanes. This proposed A would require an inspection of the elevator and aileron trim-tab fittings, and related investigative/corrective actions if necessary. This proposed AD is prompted by reports of improperly installed rivets in the retainers that hold the elevator trim-tab bearings. We are proposing this AD to prevent the elevator and aileron trim-tab bearings from coming loose, which could result in excessive play in the elevator and aileron trim systems, and reduced controllability of the airplane.

DATES: We must receive comments on this proposed AD by [insert date 30 days after date of publication in the FEDERAL REGISTER].

ADDRESSES: Use one of the following addresses to submit comments on this proposed AD.

- DOT Docket web site: Go to http://dms.dot.gov and follow the instructions for sending your comments electronically.
- Government-wide rulemaking web site: Go to http://www.regulations.gov and follow the instructions for sending your comments electronically.

OFFICIAL FILE COPY

OUTING SYMBOL DNM116 Bob primile f

CONCURRENCES

ROUTING SYMBOL

ANM-100

DATE

ROUTING SYMBOL

INITIALS/SIGNATURE